


SR. NO-1 5

DATE: 22/09/2026

SCHOOL BUILDING SAFETY CERTIFICATE

It is certified that building of the school named as NEW ERA PUBLIC SCHOOL, located at Ravapar-Ghunda Road, Nr. Ravapar Village, Morbi-363 641 (Gujarat) is in sound, safe and stable condition. I visited the site on **18/09/2026** from the available documents, I read that RCC frame structure is there. Building is earthquake resistant and safe from all the point of view. This Certificate is provided to whom it may concern.

Building residual life approx. **5 years from today & then safe if repaired and maintain regularly.**



Er. Chirag R. Pandya
(B.E. Civil)
LIC. : 457SE21043110020

FORM NO.

Certificate of Stability for Continued Use of School

1. Name of the Building: NEW ERA PUBLIC SCHOOL (English Medium)
2. Address: Ravapar-Ghunada Road, Nr. Ravapar Village,
Morbi
3. Phone No. /Email : 97127 11888 / newerapublicschool2004@yahoo.com
4. Name of the Occupier of the Premises: SAHYOG DEVELOPERS
5. Use of Occupancy: EDUCATIONAL
6. No. of floors: 2 FLOORS

I certify that I have inspected the premises, the plans of which have been approved by the Municipal Corporation (or other relevant authority) of ___ vide ___ dated ___ and have reviewed it internally and externally. I am of the opinion that the structure of the said premises appears in sound condition and that its /their stability will not be endangered by its continued use for which the building was intended.

Attached is my Survey Report.

Signature: 

Qualifications: B.E. Civil

Experience: 09 years

Affiliations/Memberships to Professional Associations:

Licence No. of Municipal Corporation (if not applicable, membership no of IIE)

Address:

Er. Chirag R. Pandya
(B.E. Civil)

Date:

LIC. : 457SE21043110020

10.0 SCHOOL SURVEY FORM

1.	School Name	NEW ERA PUBLIC SCHOOL
2.	School ID	EXTENSION APPLICATION
3.	School category (Pre-Primary - A, Primary- B, Secondary – C, Higher secondary – D)	D
4.	Address a) Location b) Village/Town/City: c) Census Code: d) Taluka: e) District: f) Nearest Town	Ravapar-Ghunada Road, Nr. Ravapar Village, Morbi Morbi Morbi Morbi
5.	GPS Coordinates of School (Any center point)	<u>22.742355</u> N <u>70.813072</u> E <u>120.5</u> m
6.	Communication System a) Telephone b) Fax c) Internet / Email d) Any other emergency communication facility	9712711888 newerapublicschool2004@yahoo.com 9712711888
7.	School Area (meter square) a) Plot Area: b) Footprint Area: c) built up Area	8094.00 mts
8.	Number of (indicate as per shifts if any) a) Pupils b) Teachers c) Other Staff d) Physically challenged staff	1007 47 05 -
9.	Number of Rooms a) Class Rooms b) Other Rooms	51 13

10.	Passage and Veranda a) Width of Passages (Less than 1.5m) b) Veranda Area (In m2)	3m
11.	Width of Stair flight (m)	1.5 mtr
12.	Number of Exit	TWO
13.	Compound Wall (Yes/No, If yes then height of wall)	YES – 4 FEET
14.	Year of Construction	2004
15.	Plan shape : Draw Plan and elevation with major dimensions (See also last sheet)	
	Please find attached building plans & general plans	
16.	Plan Regular/ Irregular : U- Shape Regular If irregular. T- shape/L-shape/U-shape/Cruciform/other complex shape:	

17.	Number of storeys : a) Basement (Yes / No) b) Storeys c) Mezzanine (Yes / No)	YES YES -
18.	Typical storey height (m)	4 mtr
19.	Stilt at Ground floor: (Yes/No)	-
20.	Type of load carrying system : a) Stone Masonry Bearing walls b) Brick Masonry Bearing walls c) RCC Frames d) Steel Structure e) Other (elaborate)	RCC FRAMES
21.	Partition walls : Reinforced concrete/ Wood/ Masonry/ Mixed/ Other(Specify)	Reinforced Concrete
22.	Floor slabs : Reinforced concrete/Wood/Other(Specify)	<i>Reinforced concrete structure</i>
23.	Floor Finish: Wood/ Ceramic/ Mosaic /IPS/ Other(specify)	Ceramic
24.	Roof : Reinforced concrete flat roof/ Reinforced concrete sloping roof/ Wood/Asbestos/Metal sheets/ Other (Specify)	REINFORCED CONCRETE FLAT ROOF
25.	Seismic/other disaster safety features in the building(in case of masonry) a) Plinth Band b) Lintel Band c) Roof Band d) Other features Seismic/other disaster safety features	N/A

	in the building(in case of RC frame) a) Proper framing grid of more than 3 frames of min 3 bays each in both direction b) Max cantilever projection (m) c) Any floating columns? If yes, give details	a) Proper framing grid of more than 3 frames of min 3 bays in both direction - yes b) 0 m c) NO
26.	Quality of Building a) Workmanship b) Maintenance Grade on a scale of 5) (5 for excellent and 1 for poor)	WORKMANSHIP 04
27.	Any Existing visible damages (Yes/No) If yes: Description	NO
28.	Last repair & reconstruction works a) Repaired (Year) b) Strengthened (Year)	2012
29.	Fire Protection : (Yes / No) a) High voltage electric transformers not protected within campus or 25m periphery of school - NO b) Loose electric wares within campus and not fenced - NO c) Any highly flammable/ hazardous goods lying in the school or surrounding buildings d) Petrol Pump (25m periphery of school) - NO e) Hydrants (Yes / No) f) Fire extinguishers (Yes / No) g) Fire Alarms (Yes / No) h) Smoke detectors(Yes/No) i)	YES - FIRE PROTECTED NO NO NO NO YES YES ~~NO~~ yes NO
30.	Surroundings of School a) High Rise/Low Rise Buildings - NO b) Congested/Market Area - NO c) High traffic/Normal traffic/ Low traffic Area	Low Rise Low Traffic Area
31.	Technical documentation available a) Architecture (Yes / No) b) Structural design (Yes / No)	YES YES

32.	Site – Soil conditions : Rock/Firm/Medium/Soft	- <i>Firm</i>
33.	Slope :Flat /Slight slope/Moderate slope/Steep slope	SLIGHT
34.	Seismic exposure : (To be filled by Reviewing Engineer) a) Seismic Zone b) Unknown	<i>Zone - 5 (old zone - 4)</i>
35.	History of Disaster (Mention month, year, frequency and damages due to the disaster) a) Earthquake b) Cyclone c) Floods d) Fire	- NO -
36.	Awareness in School a) Among Teachers b) Among Students c) Any Formal course/training for disasters	YES
37.	Preparedness for Disasters a) Contingency plan b) Escape Routes c) Safe Shelters during cyclone d) Other preparedness	YES
38.	Photographs	AS ATTACHED
39.	Remarks & recommendations (Yes /No)	<i>NO</i>

The above parameters are indicative and interested consultant may comment to achieve the objective of study.

Surveyor

Name: **Er. Chirag R. Pandya**
(B.E. Civil)
Signature: **LIC.: 457SE21043110020**

Date:

Building ID
(Line Plan of the School Campus and building IDs)

Principal / TRUSTEE

Name: **DR. SEEMAN D. JADEJA**
Signature:

PRINCIPAL
NEW ERA PUBLIC SCHOOL
MORBI